

**To:** CN=Ayn Schmit/OU=R8/O=USEPA/C=US@EPA[]  
**Cc:** CN=David Jewett/OU=ADA/O=USEPA/C=US@EPA;"Rick Wilkin" [wilkin.rick@epa.gov]; Rick Wilkin" [wilkin.rick@epa.gov]  
**From:** CN=Dominic DiGiulio/OU=ADA/O=USEPA/C=US  
**Sent:** Mon 9/24/2012 9:52:36 PM  
**Subject:** info Tribal Pavillion 14-01

Hydraulic fractured occurred in the Wind River Formation at a depth as shallow as 322.5 m (1058 ft) below ground surface (bgs) or 1311 m AMSL at Tribal Pavillion 14-01. In the draft EPA report (EPA 2011), it was reported that hydraulic fracturing occurred as shallow as 372 m (1220 ft) bgs.

Dominic C. DiGiulio, Ph.D.

U.S. Environmental Protection Agency  
Office of Research and Development  
National Risk Management Research Laboratory  
Ground Water and Ecosystem Restoration Division  
919 Kerr Research Drive  
Ada, Oklahoma 74820

580-436-8605 (phone)  
580-436-8614 (fax)  
580-583-7329 (mobile)